



Control Number: 50594



Item Number: 11

Addendum StartPage: 0



## Public Utility Commission of Texas

### Five-Year Report

Required by 16 Texas Admin. Code § 25.97(e)

FILED  
2020 APR 27 AM 11:14  
TSCC DISTRICT CLERK  
FILING CLERK

**PROJECT NO.** 50594

**AFFECTED ENTITY:** Wood County Electric Cooperative, Inc.

#### General Information

Pursuant to 16 Texas Admin. Code § 25.97(e)(1), not later than May 1 every five years, each affected entity that owns or operates overhead transmission facilities greater than 60 kilovolts must submit this report. The first report must be submitted not later than May 1, 2020.

#### Instructions

Answer all questions, fill-in all blanks, and have the report notarized in the Affidavit.

#### Affidavit

A representative of the affected entity must swear to and affirm the truthfulness, correctness, and completeness of the information provided by attaching a signed and notarized copy of the Affidavit provided with this form.

#### Filing Instructions

Submit four copies (an original and three copies) of the completed form and signed and notarized Affidavit to:

Central Records Filing Clerk  
Public Utility Commission of Texas  
1701 N. Congress Avenue  
P.O. Box 13326  
Austin, Texas 78711-3326  
Telephone: (512) 936-7180

1

**1. Historical five-year reporting period:** 2014 - 2019

What percentage of overhead transmission facilities greater than 60 kilovolts did you inspect for compliance with the National Electric Safety Code (NESC) relating to vertical clearance in the historical five-year reporting period?

In December 2019 a detailed inspection on 83% of the transmission system was performed. This data is currently being evaluated and field verified to determine if there are actual NESC vertical clearance violations.

Wood County Electric Cooperative performs an annual inspection of 100% of the transmission system by helicopter. This inspection includes observing the condition of the structures and related hardware, ensuring wire attachment points are intact, and the general condition of the right-of-way.

**2. Future five-year reporting period:** 2020 - 2024

What percentage of overhead transmission facilities greater than 60 kilovolts do you anticipate you will inspect for compliance with the NESC relating to vertical clearance during the future five-year reporting period beginning on January 1 of the year in which this report is submitted?

In 2020 a detailed inspection on remaining the 17% of the transmission system will be conducted.


Wood County Electric Cooperative will continue to perform annual helicopter inspections over all the transmission system to observe the condition of the structures and related hardware, ensuring wire attachment points are intact, and the general condition of the right-of-way.

Affected Entity: Wood County Electric Cooperative, Inc.

PROJECT NO. 50594

## AFFIDAVIT

I swear or affirm that I have personal knowledge of the facts stated in this report or am relying on people with personal knowledge, that I am competent to testify to them, and that I have the authority to submit this report on behalf of the affected entity. I further swear or affirm that all statements made in this report are true, correct, and complete.


  
Signature


CLIFF H. CAMPBELL  
Printed Name

CHIEF OPERATING OFFICER  
Job Title

WOOD COUNTY ELECTRIC CO-OP  
Name of Affected Entity

Sworn and subscribed before me this 24 day of April, 2020.  
Month Year



  
Notary Public in and For the State of Texas

My commission expires on December 2, 2021